

5 **METHOD FOR MONITORING WOOD-DRYING KILN** **STATE**

Abstract

10 The method utilizes a known good set of moisture content data for wood dried in
a kiln under set conditions to estimate parameters for a Lognormal distribution which
approximates the moisture content data for those conditions. The method creates control
charts which monitor some of these parameters. The method also takes data from
subsequent kiln charges and transforms it to be represented on the control charts. The
method uses this representation to determine if the kiln is operating under out-of-control
15 conditions.